AAA Home Inspections

Property Inspection Report



4808 Pepperwood Way, San Jose CA, 95124 Inspection prepared for: Karin Dillin & Natalie Kraten Agent: Stacy Seymour - Coldwell Banker

Inspection Date: 6/11/2011 Time: 11:00

Inspector: Jim Pillsbury
1095 Fleetwood Dr, San Jose, CA, 95120
Phone: 408-839-2467
Email: jimpillsbury@gmail.com
www.asanjosehomeinspector.com

Report Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expenses to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all of the pages of the report as the summary alone does not explain all the issues. All repairs must be done by a licensed &bonded trade or profession. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

Interior Areas	nterior Areas					
Page 7 Item: 7	Electrical	 2-prong outlets - The home contained outdated, ungrounded 2-prong electrical outlets. Although this condition may have been commonly considered safe or acceptable at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing condition to meet generally-accepted current standards. 				

Page 13 Item: 7

Electrical

• 2-prong outlets -

The home contained outdated, ungrounded 2-prong electrical outlets. Although this condition may have been commonly considered safe or acceptable at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing condition to meet generally-accepted current standards.

 No Arc-Fault Circuit Interrupter (AFCI) protection was installed to protect electrical circuits in bedrooms.
 Building codes with which new homes must comply require the installation of AFCI protection of all bedroom outlets. This type of protection is designed to detect electrical arcing, which is a potential fire hazard.

Although AFCI protection was not required at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing electrical to provide AFCI protection.

Arc-fault protection can be provided using either of two methods:

- 1. Arc Fault Circuit Interrupters (AFCI's) electrical outlets which have this capability built in.
- 2. AFCI circuit breakers installed at the main electrical panel which provide this protection to all non-AFCI outlets on the circuit controlled by that AFCI breaker.

2-prong outlets -

The home contained outdated, ungrounded 2-prong electrical outlets. Although this condition may have been commonly considered safe or acceptable at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing condition to meet generally-accepted current standards.

 No Arc-Fault Circuit Interrupter (AFCI) protection was installed to protect electrical circuits in bedrooms.
 Building codes with which new homes must comply require the installation of AFCI protection of all bedroom outlets. This type of protection is designed to detect electrical arcing, which is a potential fire hazard.

Although AFCI protection was not required at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing electrical to provide AFCI protection.

Arc-fault protection can be provided using either of two methods:

1. Arc Fault Circuit Interrupters (AFCI's) electrical outlets which have this capability built in.

		2. AFCI circuit breakers installed at the main electrical panel
		which provide this protection to all non-AFCI outlets on the circuit controlled by that AFCI breaker.
		• 2-prong outlets - The home contained outdated, ungrounded 2-prong electrical outlets. Although this condition may have been commonly considered safe or acceptable at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing condition to meet generally-accepted current standards.
		 No Arc-Fault Circuit Interrupter (AFCI) protection was installed to protect electrical circuits in bedrooms. Building codes with which new homes must comply require the installation of AFCI protection of all bedroom outlets. This type of protection is designed to detect electrical arcing, which is a potential fire hazard. Although AFCI protection was not required at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing electrical to provide AFCI protection. Arc-fault protection can be provided using either of two methods: 1. Arc Fault Circuit Interrupters (AFCI's) electrical outlets which have this capability built in. 2. AFCI circuit breakers installed at the main electrical panel which provide this protection to all non-AFCI outlets on the circuit controlled by that AFCI breaker.
Kitchen		
Page 26 Item: 24	GFCI	• GFCI tested and found to be improperly wired. Recommend review and repair by Qualified Electrician, there were no grounds present at GFI receptacles. Recommend running a ground wire back to the panel.
Heat/AC		
Page 29 Item: 2	Heater Base	The heater base shows signs of water damage. Possible prior water intrusion.
Garage		
Page 36 Item: 1	Roof Condition	 Flashing at gable above garage and around chimney are lifting. Recommend fastening the flashing to the roof deck and caulking around the flashings
Page 37 Item: 4	Floor Condition	Spalling noted at front of garage, recommend repairing
Page 37 Item: 6	Electrical	 Most receptacles in house were 2 prong outlets and not grounded. I recommend grounding the outlets
Electrical		

			, •
Λ	HOMO	Ingno	CTIONS
	Home		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			

4808 Pepperwood Way, San Jose , CA

Page 40 Item: 1	Electrical Panel	• There is a Zinsco service panel present. Zinsco components are prone to problems that can lead to failures, lack of proper protection of circuits and other serious issues, including fire and electrocution. We cannot definitively call this panel defective, but recommend, for your peace of mind, to consult a qualified electrical contractor to get their opinion on this matter. You can learn more about this issue at
		matter. You can learn more about this issue at http://www.inspect-ny.com/electric/zinsco.htm
		 Panel cover missing, exposing live electrical wires as an electrocution hazard.

Inspection Details

1. Attendance	
	In Attendance: Client present • Fully Participated
2. Home Type	
	Home Type: Single Family Home • Ranch Style
3. Occupancy	
	Occupancy: Vacant • The utilities were on at the time of inspection.

Interior Areas

The Interior section covers areas of the house that are not considered part of the Bathrooms, Bedrooms, Kitchen or areas covered elsewhere in the report. Interior areas usually consist of hallways, foyer, and other open areas. Within these areas the inspector is performing a visual inspection and will report visible damage, wear and tear, and moisture problems if seen. Personal items in the structure may prevent the inspector from viewing all areas on the interior.

The inspector does not usually test for mold or other hazardous materials. A qualified expert should be consulted if you would like further testing.

1. Bar

Good	Fair	Poor	N/A	None
				_
				^

2. Cabinets


Good	Fair	Poor	N/A	None
				Х

3. Ceiling Fans

Good	Fair	Poor	N/A	None	Ol
					Observations:
					 None present.

4. Closets

Good	Fair	Poor	N/A	None	Ob
					Observations:
X					• The closet is in serviceable condition.



5. Door Bell

_ G	ood	Fair	Poor	N/A	None
					Х

6. Doors

Good	Fair	Poor	N/A	None
Х				



Front entry

7	F	lectrical
1.		Collica

. ^	None	N/A	Poor	Fair	Good
ĮΟ					
T .			I I		

Observations:

• 2-prong outlets The home contained outdated, ungrounded 2-prong electrical outlets.
Although this condition may have been commonly considered safe or acceptable at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing condition to meet generally-accepted current standards.

8. Security Bars

	Oudu	ı an	1 001	11//	INOITE
ı					
ı					
ı					
ı					
ı					

Observations:

No security bars are present in this room.

9. Smoke Detectors

Good	Fair	Poor	N/A	None
				V
		l		_ ^
1			ı	

10. Stairs & Handrail

Good	Fair	Poor	N/A	None
			Х	

11. Window-Wall AC or Heat

Good	Fair	Poor	N/A	None
			\ \	
			X	

12. Window Condition

0000	i ali	1 001	14/7	INOILE	. Mataviala, Missyl fususa al alialis syvils alavy sata al a lisavylata al sila as sata
					Materials: Vinyl framed sliding window noted. • Insulated glass note
l		l .			materiale tilly hamed ending milden heteur inediated glace hete
l		l .			
l		l .			



13. Ceiling Condition

Good	Fair	Poor	N/A	None	Matariala. Thans and during the allie of restant
Χ					Materials: There are drywall ceilings noted
X					

14. Patio Doors

Good	Fair	Poor	N/A	None
				Х



Patio doors in dining area

15. Screen Doors

	Good	Fair	Poor	N/A	None
					Χ
ı					

16. Wall Condition

Good	Fair	Poor	N/A	None	
					ı Ma
X		l	l	l	
		ı	ı	l .	l

Materials: Drywall walls noted.



Dining area

Tile entry noted

17. Fireplace

Good	Fair	Poor	N/A	None
Х				

Materials: Living Room Materials: Masonry fireplace noted. Observations:

• Damper was opened and closed several times.



Hardwood floors noted

Fireplace located in living room

Bedrooms

The main area of inspection in the bedrooms is the structural system. This means that all walls, ceilings and floors will be inspected. Doors and windows will also be investigated for damage and normal operation. Personal items in the bedroom may prevent all areas to be inspected as the inspector will not move personal items.

1. Locations

Locations: Master#1 • Hall#2 • Hall

2. Bar

Good	Fair	Poor	N/A	None
	•			
				X

3. Cabinets

Good	Fair	Poor	N/A	None
				Х

4. Ceiling Fans

Guuu	ı alı	FUUI	11/7	INOHE	Ol
					Observations:
					 None present.
					• None present.

5. Closets

Good	Fair	Poor	N/A	None
X				

Observations:

- The closet is in serviceable condition.
- The closet is in serviceable condition.
- The closet is in serviceable condition.





Master bedroom closet

6. Doors

7. Electrical

Good	Fair	Poor	IN/A	None

Observations:

• 2-prong outlets -

The home contained outdated, ungrounded 2-prong electrical outlets. Although this condition may have been commonly considered safe or acceptable at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing condition to meet generally-accepted current standards.

• No Arc-Fault Circuit Interrupter (AFCI) protection was installed to protect electrical circuits in bedrooms.

Building codes with which new homes must comply require the installation of AFCI protection of all bedroom outlets. This type of protection is designed to detect electrical arcing, which is a potential fire hazard.

Although AFCI protection was not required at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing electrical to provide AFCI protection.

Arc-fault protection can be provided using either of two methods:

- 1. Arc Fault Circuit Interrupters (AFCI's) electrical outlets which have this capability built in.
- 2. AFCI circuit breakers installed at the main electrical panel which provide this protection to all non-AFCI outlets on the circuit controlled by that AFCI breaker.

2-prong outlets -

The home contained outdated, ungrounded 2-prong electrical outlets. Although this condition may have been commonly considered safe or acceptable at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing condition to meet generally-accepted current standards.

• No Arc-Fault Circuit Interrupter (AFCI) protection was installed to protect electrical circuits in bedrooms.

Building codes with which new homes must comply require the installation of AFCI protection of all bedroom outlets. This type of protection is designed to detect electrical arcing, which is a potential fire hazard.

Although AFCI protection was not required at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing electrical to provide AFCI protection.

Arc-fault protection can be provided using either of two methods:

- 1. Arc Fault Circuit Interrupters (AFCI's) electrical outlets which have this capability built in.
- 2. AFCI circuit breakers installed at the main electrical panel which provide this protection to all non-AFCI outlets on the circuit controlled by that AFCI breaker.

2-prong outlets -

The home contained outdated, ungrounded 2-prong electrical outlets.

Although this condition may have been commonly considered safe or acceptable at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing condition to meet generally-accepted current standards.

• No Arc-Fault Circuit Interrupter (AFCI) protection was installed to protect electrical circuits in bedrooms.

Building codes with which new homes must comply require the installation of AFCI protection of all bedroom outlets. This type of protection is designed to detect electrical arcing, which is a potential fire hazard.

Although AFCI protection was not required at the time the home was originally constructed, as general knowledge of safe building practices has improved with the passage of time, building standards have changed to reflect current understanding. Consider updating the existing electrical to provide AFCI protection.

Arc-fault protection can be provided using either of two methods:

- 1. Arc Fault Circuit Interrupters (AFCI's) electrical outlets which have this capability built in.
- 2. AFCI circuit breakers installed at the main electrical panel which provide this protection to all non-AFCI outlets on the circuit controlled by that AFCI breaker.

8. Fireplace

Fair	Poor	N/A	None
			X
	· u.i	1 4.1 1 55.	1 00. 147.

9. Floor Condition

Good	Fair	Poor	N/A	None	. El a a alta at T a .
					Flooring Types
X					

Flooring Types: Hardwood flooring is noted.



10. Security Bars

	Good	Fair	Poor	N/A	None
ı					
ı			l		
ı			l		
ı					

Observations:

- No security bars are present in this room.
- No security bars are present in this room.
- No security bars are present in this room.

11. Smoke Detectors

Good	Fair	Poor	N/A	None	
					Observations:
					• There were no smoke detectors present in the bedroom(s).
		•		•	No smoke/ fire detectors were installed at time of inspection

12. Wall Condition

Good	Fair	Poor	N/A	None	
					Material
X			l		

Materials: Drywall walls noted.



13. Window-Wall AC or Heat

Good	Fair	Poor	N/A	None
			Χ	

14. Window Condition

Good	Fair	Poor	N/A	None	Matariala Visul franca dali dispersionale e del del del del del del del del del
<					Materials: Vinyl framed sliding window noted. • Insulated glass noted.
_ ^			l	l	





15. Ceiling Condition

X

Materials: There are drywall ceilings noted.

16. Patio Doors

Good	Fair	Poor	N/A	None
				Х

17. Screen Doors

Good	Fair	Poor	N/A	None
				ΙV
				^

Bathroom

Bathrooms can consist of many features from jacuzzi tubs and showers to toilets and bidets. Because of all the plumbing involved it is an important area of the house to look over. Moisture in the air and leaks can cause mildew, wallpaper and paint to peel, and other problems. The home inspector will identify as many issues as possible but some problems may be undetectable due to problems within the walls or under the flooring..

1. Locations

Locations: Master Bathroom • Full bath

2. Cabinets

Good	Fair	Poor	N/A	None	
Х				Х	

Observations:

- No deficiencies observed.
- Appeared functional and in satisfactory condition, at time of inspection.





3. Ceiling Condition

Good	Fair	Poor	N/A	None
Х				

Materials: There are drywall ceilings noted.

4. Counters

Good	Fair	Poor	N/A	None
Χ				Х

Observations:

Solid Surface tops noted.

5. Doors

Good	Fair	Poor	N/A	None
Х				

Observations:

- No major system safety or function concerns noted at time of inspection.
- No major system safety or function concerns noted at time of inspection.

6. Electrical

Good	Fair	Poor	N/A	None
Х				

Observations:

- No major system safety or function concerns noted at time of inspection.
- No major system safety or function concerns noted at time of inspection.

7. GFCI

Good	Fair	Poor	N/A	None
Х				

Observations:

- GFCI in place and operational
- GFCI in place and operational

8. Exhaust Fan

Good	raii	P001	IN/A	None	
					Observations:
Х					• The bath fan was operated and no issues were found.
					• The bath fan was operated and no issues were found

9. Floor Condition

Good	Fair	Poor	N/A	None	
					Mate
Χ					

Materials: Sheet vinyl flooring is noted.



10. Heating

Good	Fair	Poor	N/A	None
			Χ	

11. Mirrors

Good	Fair	Poor	N/A	None
Χ	Χ			



Bathroom cabinets noted

AAA Home Inspections

12. Plumbing

Good	Fair	Poor	N/A	None
Х				
1 ' '				

13. Security Bars

Good	Fair	Poor	N/A	None
				V
				^

14. Showers

Good	Fair	Poor	N/A	None	Ob
					Observations:
X			l	ΙX	l • functional



15. Shower Walls

Good	raii	Poor	IN/A	none	. Ot
					Observations:
X					• Ceramic tile noted.
					• Ceramic tile noted.

16. Bath Tubs

Good	Fair	Poor	N/A	None
				Х



17. Enclosure

	Good	Fair	Poor	N/A	None	
- [Observations:
-	Χ					• The shower enclosure was functional at the time of the inspection.

Curtain present at the shower enclosure.



18. Sinks

Good	Fair	Poor	N/A	None	Ob
					ן Observations:
X					No deficiencies observed.
					• No deficiencies observed.





19. Toilets

Good	Fair	Poor	N/A	None
				l
				l
				ı

Observations:

- Operated when tested. No deficiencies noted.
 Operated when tested. No deficiencies noted.





Lino floor noted

20. Window Condition

Good	Fair	Poor	N/A	None
X				
^				

Materials: Vinyl framed sliding window noted. • Insulated glass noted.



Kitchen

The kitchen is used for food preparation and often for entertainment. Kitchens typically include a stove, dishwasher, sink and other appliances.

1. Cabinets

G00a_	Fair	Poor	IN/A	None
	V	l		
	X			

Observations:

• Appeared functional and in satisfactory condition, at time of inspection.



2. Counters

Good	Fair	Poor	N/A	None
X				
_ /\		l .		

Observations:

• Granite tops noted.



Pantry

3. Dishwasher

Good	Fair	Poor	N/A	None	Ob
					Observations:
X					operated



4. Doors

	Good	Fair	Poor	N/A	None
		Y			
ı			l .		

Observations:

• No major system safety or function concerns noted at time of inspection.

5. Garbage Disposal

Good	Fair	P001	IN/A	none
X				

Observations:

• Operated - appeared functional at time of inspection.

6. Microwave

Good	Fair	Poor	N/A	None
				ΙXΙ
				_ ^ _

7. Cook top condition

Good	Fair	Poor	N/A	None	01
					Observations:
X					• Electric cook top noted.

8. Oven & Range

Good	Fair	Poor	N/A	None
Х				

Observations:

- Oven(s): ElectricAll heating elements operated when tested.



9. Sinks

Good	Fair	Poor	N/A	None	Olas a de la constanta de la c
					Observations:
X					 No deficiencies observed.

10. Drinking Fountain

Guuu	ı alı	FUUI	11//	INOHE

Observations:

• There was no drinking fountain present in this kitchen.

11. Spray Wand

Good	Fair	Poor	N/A	None
Х				

Observations:

- There was no spray wand present in this kitchen.
- There was no spray wand but there was a spray head present

12. Hot Water Dispenser

Good	Fair	Poor	N/A	None
				ΙXΙ

13. Soap Dispenser

X	

Observations:

• The soap dispenser was functional.


14. Trash Compactor

Good	Fair	Poor	N/A	None
				V
				^

15. Vent Condition

Good	Fair	Poor	N/A	None
Х				

Materials: Exterior Vented



16. Window Condition

Good	Fair	Poor	N/A	None
Х				

Materials: Vinyl framed single hung window noted. • Insulated glass noted.



Upper cabinets noted

17. Floor Condition

	Good	Fair	Poor	N/A	None	Metarials Commistile is noted in hitches divisor and front out-
Г	`,					Materials: Ceramic tile is noted in kitchen, dining area and front entry
	$X \mid$		l			

18. Plumbing

Good	Fair	Poor	N/A	None
Х				

19. Ceiling Condition

Good	Fair	Poor	N/A	None	Matariala. Thans are during the cities as water t
					Materials: There are drywall ceilings noted.
X					

20. Security Bars

Good	Fair	Poor	N/A	None	
					Observations:
					 No security bars are present in this room.

21. Patio Doors

Observations: **Sliding Patio Doors** The cliding patio door was functional during the inspection	(Good	Fair	Poor	N/A	None	Observations
		Х					Observations:
▼ THE SHOULD DAND DOOL WAS HITCHOLD HOURD THE HISDECHO	L	^					• The sliding patio door was functional during the inspection.

22. Screen Doors

Good	Fair	Poor	N/A	None	Observations.
					Observations:
X					 Sliding door screen is functional.

23. Electrical

Observations:	
X • No major system safety or fu	unction concerns noted at time of inspection.

AAA Home Inspections

4808 Pepperwood Way, San Jose, CA

24. GFCI

Good	Fair	Poor	N/A	None

Observations:

- GFCI protected receptacles may not have been required when the house was built. We suggest buyer consider upgrading with GFCI's at all receptacles near water sources.
- receptacles near water sources.

 GFCI tested and found to be improperly wired. Recommend review and repair by Qualified Electrician, there were no grounds present at GFI receptacles. Recommend running a ground wire back to the panel.

25. Wall Condition

Good	Fair	Poor	N/A	None
Х				

Materials: Drywall walls noted.

Laundry
1. Locations
2. Cabinets Good Fair Poor N/A None
Good Fair Poor N/A None
3. Counters
Good Fair Poor N/A None
4. Dryer Vent
Good Fair Poor N/A None
5. Electrical
Good Fair Poor N/A None
6. GFCI
Good Fair Poor N/A None
7. Exhaust Fan
Good Fair Poor N/A None
8. Gas Valves
Good Fair Poor N/A None
9. Wash Basin
Good Fair Poor N/A None
10. Window Condition Good Fair Poor N/A None
GOOD TAIL FOOT TWA NOTICE
11. Floor Condition
Good Fair Poor N/A None
12. Plumbing
Good Fair Poor N/A None

AAA Home Inspections	4808 Pepperwood Way, San Jose , CA
13. Wall Condition	
Good Fair Poor N/A None	
14. Ceiling Condition Good Fair Poor N/A None	
15. Security Bars Good Fair Poor N/A None	
16. Doors Good Fair Poor N/A None	

Heat/AC

The heating, ventilation, and air conditioning and cooling system (often referred to as HVAC) is the climate control system for the structure. The goal of these systems is to keep the occupants at a comfortable level while maintaining indoor air quality, ventilation while keeping maintenance costs at a minimum. The HVAC system is usually powered by electricity and natural gas, but can also be powered by other sources such as butane, oil, propane, solar panels, or wood.

The inspector will usually test the heating and air conditioner using the thermostat or other controls. For a more thorough investigation of the system please contact a licensed HVAC service person.

1. Heater Condition

Good	Fair	Poor	N/A	None	National Color Theorem Color and Col
					Materials: The furnace is located in the hall closet
X					Materials: Gas fired forced hot air



2. Heater Base

T	1	T	T	ן Observations:
				• The heater base shows signs of water damage. Possible prior water
				intrusion



Past staining noted at heater base, could not locate where leakage was coming from

3. Enclosure

Fair	Poor	N/A	None
		l	ΙX
	Fair	Fair Poor	Fair Poor N/A

4. Venting

Good	Fair	Poor	N/A	None
Χ				

Observations:

• The visible portions of the vent pipes appeared functional.

5. Gas Valves

Good	Fair	Poor	IN/A	None
V				
_ ^				

Observations:

• Gas shut off valves were present and functional.



6. Refrigerant Lines

	Good	Fair	Poor	N/A	None
I	V				
ı		I	ı	I	I

Observations:

No defects found.



7. AC Compress Condition

Good	Fair	Poor	N/A	None	~ · · · · · · · · · · · · · · · · · · ·
Х					Compressor Type: electric Location: The compressor is located near the patio area.
					Observations:

Appeared functional at the time of inspection.



8. Air Supply

Good	Fair	Poor	N/A	None	
					Observations:
X					• The return air supply system appears to be functional.

9. Registers

Good	Fall	FUUI	IN/A	None	
					Observations:
1 🗤					
I X					 The return air supply system appears to be functional.
1 ' '					The retain an eapply eyetem appears to be randitional.

10. Filters

_ (-	5 00a	Fair	Poor	N/A	None	I anathem I anatod booked beaten arbinat of anatod by a filter will be an interior.
						Location: Located inside heater cabinet. • Located in a filter grill in an interior
	Х					area wall.

11. Thermostats

Good	Fair	Poor	N/A	None	Observations
					Observations:
					Digital - programmable type.
					• Functional at the time of inspection.



Water Heater

1. Base

	Good	Fall	FUUI	IN/A	None	Observations.
ı						Observations:
	Χ					The water heater base is functional.



2. Heater Enclosure

Good	Fair	Poor	N/A	None
				Χ

3. Combusion

Good	Fair	Poor	N/A	None	
					Observations:
Χ					• The combustion chamber appears to in functional condition.

4. Venting

Good	Fair	Poor	N/A	None
Χ				

5. Water Heater Condition

Good	Fair	Poor	N/A	None	. U
					ן Heater Type: gas
Х					Location: The heater is located in the garage.
					Ohservations:

- Tank appears to be in satisfactory condition -- no concerns.
- A Temperature Pressure Relief (TPR) valve present. This safety valve releases water (and thus relieves pressure) if either the temp or pressure in the tank gets too high. The TPR valve discharge tube must be made of copper, iron, or CPVC (NOT regular PVC). It must terminate within 6" above the floor--the end cannot be threaded or have a fitting.
- No deficiencies noted with the Temperature Pressure Relief (TPR) valve and discharge pipe.



6. TPRV

Good	Fair	Poor	N/A	None
Х				

Observations:

• Appears to be in satisfactory condition -- no concerns.



7. Number Of Gallons

Good	Fair	Poor	N/A	None	Ol
					Observations
X					 40 gallons

8. Gas Valve

Good	Fair	Poor	N/A	None
Х				

9. Plumbing

Good	Fair	Poor	N/A	None	NA. (. 2 . 1
					Materials: copper • galvanized
X					Observations:

• No deficiencies observed at the visible portions of the supply piping.



10. Overflow Condition

Good	Fair	Poor	N/A	None	NA de Cala de la casa
					Materials: copper
X					Observations:

Appears to be in satisfactory condition -- no concerns.

11. Strapping

Good	Fair	Poor	N/A	None
Χ				

Garage

1. Roof Condition

Good	Fair	Poor	N/A	None
	Х			
	٠.			

Materials: Inspected from roof

Materials: Composition shingles noted.

Observations:

• Clean roof areas: Significant amounts of organic debris evident. Roof appears to right around 10-12 years old

• Flashing at gable above garage and around chimney are lifting. Recommend fastening the flashing to the roof deck and caulking around the flashings

2. Walls

Good	Fair	Poor	N/A	None
Х				

Observations:

Appeared satisfactory, at time of inspection.



3. Anchor Bolts

Goo	oa	Fair	Poor	N/A	None
X					

Observations:

• The anchor bolte were inspected and appear to be serviceable.

4. Floor Condition

Good	Fair	Poor	N/A	None

Materials: Bare concrete floors noted.

Observations:

Spalling noted at front of garage, recommend repairing



5. Rafters & Ceiling

	Good	Fair	Poor	N/A	None
ſ					
I	Χ			l	

Observations:

• Dimensional lumber wood ceiling joists

6. Electrical

Good	Fair	Poor	N/A	None
	Х			

Observations:

 Most receptacles in house were 2 prong outlets and not grounded. I recommend grounding the outlets

7. GFCI

Good	ood Fair Poor		N/A	None

Observations:

• GFCI protected receptacles may not have been required when the house was built. We suggest buyer consider upgrading with GFCI's at all receptacles near water sources.

8. 240 Volt

Good	Fair	Poor	N/A	None
\ \ \				
X		l	l	

Observations:

• The 240 volt outlets tested functional.

9. Exterior Door

_	Good	Fair	Poor	N/A	None
I	Χ				
ı					

Observations:

• Appeared functional, at time of inspection.

10. Fire Door

Good	Fair	Poor	N/A	None
		l		

Observations:

• There is no self-closing device on the door from the house leading to the garage. It is strongly recommended that one be installed in order to protect the residence against garage originated fires.



Door going into house needs self closing hinges

11. Garage Door Condition

Good	Fair	Poor	N/A	None	Matariala, Ora 101 un arradad inacidatad ataal daar
\ \ \					Materials: One 16' upgraded insulated steel door
X					Observations:

• No deficiencies observed.



12. Garage Door Parts

Good	ган	F001	IN/A	None	Ob
					Observations:
1 🗤		l .			
X					• The garage door appeared functional during the inspection.
'`					The garage additappeared fariotional daring the inspection.

13. Garage Opener Status

	Good	Fair	Poor	N/A	None	_
Γ						1
ı					l v	ı
ı					_ ^	ı
L						1

14. Garage Door's Reverse Status

Good	Fair	Poor	N/A	None
		l		I v I
		l		I ^ I

15. Ventilation

Good	ган	FUUI	IN/A	None	\sim 1
					Observ
X					 Under

Observations:

• Under eave soffit inlet vents noted.

16. Vent Screens

Good	Fair	Poor	N/A	None
Х				

17. Cabinets

Good	Fair	Poor	N/A	None
				ΙXΙ
				_ ^ \

18. Counters

Good	Fair	Poor	N/A	None
				Х

19. Wash Basin

	Good	Fair	Poor	N/A	None
Γ					
ı					X

Electrical

1. Electrical Panel

Good Fall Pool	IN/A	none	
			LC
			Ol

Location: Main Location: • rear of structure Observations:

There is a Zinsco service panel present. Zinsco components are prone to problems that can lead to failures, lack of proper protection of circuits and other serious issues, including fire and electrocution. We cannot definitively call this panel defective, but recommend, for your peace of mind, to consult a qualified electrical contractor to get their opinion on this matter. You can learn more about this issue at http://www.inspect-ny.com/electric/zinsco.htm
Panel cover missing, exposing live electrical wires as an electrocution hazard.



Panel needs an interior cover

2. Main Amp Breaker

Good	Fair	Poor	N/A	None	Ob
					Observations:
X					• 100 amp

3. Breakers in off position

Good	Fair	Poor	N/A	None	
					Observations:
		l	l		• 0

4. Cable Feeds

Good	Fair	Poor	N/A	None	Ob
					Observations:
Х					• There is an overhead service drop noted.

5. Breakers

Good	raii	P001	IN/A	none	. Matawala . O a maan maa matalli a alaa atla a laa la a ata d
					Materials: Copper non-metallic sheathed cable noted.
\ \Z		l	l		
X			l .		Observations:
					'a All of the circuit breekers appeared comise colo

All of the circuit breakers appeared serviceable.



Zinnsco Panel

6. Fuses

X

Roof

1. Roof Condition

Good	Fair	Poor	N/A	None





Large amounts of organic debris noted

Service drop for electrical



2. Flashing

Good	Fair	Poor	N/A	None
		l		



3. Chimney

Good	Fair	Poor	N/A	None





Chimney flashing

4. Sky Lights

Good	Fair	Poor	N/A	None
		l .		

5. Spark Arrestor

Good	Fair	Poor	N/A	None



Spark arrestor should be installed

6. Vent Caps

Good	Fair	Poor	N/A	None
				l



Sun tunnel noted

7. Gutter

Good	Fair	Poor	N/A	None
				l

Attic

1. Access

Good	Fair	Poor	N/A	None	Ob
					Observations:
X					 Bedroom Closet
	Good	Good Fair	Good Fair Poor	Good Fair Poor N/A X	



2. Structure

Good	Fair	Poor	N/A	None
Χ				



3. Ventilation

Good	Fair	Poor	N/A	None	Observations.
					Observations:
X					 Under eave soffit inlet vents noted.

4. Vent Screens

Good	Fair	Poor	N/A	None	Ob
					Observations:
Χ					 Vent screens noted as functional.

5. Duct Work

Good	Fair	Poor	N/A	None
	Χ			

Observations:

- functional
- Possible asbestos materials observed. The materials appeared to be in serviceable condition at the time of inspection. Asbestos materials are considered safe by the EPA if they are not disturbed, torn, ripped, or damaged. No torn, ripped, or damaged materials were observed. If client has any concerns regarding asbestos materials, an asbestos testing lab should be consulted for further review to ensure safety.





6. Electrical

Good	Fair	Poor	N/A	None
X				

7. Attic Plumbing

Good	Fair	Poor	N/A	None	. ,
					۱(
ΙXΙ					•

Observations:

- ABS plumbing ventsNo deficiencies noted in plumbing vent piping.

8. Insulation Condition

Good	Fair	Poor	N/A	None	Death leaded and a constant	D L
					Depth: insulation averages 3 to 4 inches.	Recommend installing more.
					Depth: Insulation averages 3 to 4 inches. Observations:	_



9. Chimney

Good	Fair	Poor	N/A	None
Х				

10. Exhaust Vent

Good	Fair	Poor	N/A	None	01
					Observations:
X					functional



Exterior Areas

1. Doors

Good	Fair	Poor	N/A	None	Observations:
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					Observations:
Х					• Appeared in functional and in satisfactory condition, at time of inspection.



2. Window Condition

Good	Fair	Poor	N/A	None	
					Observations:
X					• No major system safety or function concerns noted at time of inspection.



3. Siding Condition

Good	raii	Poor	IN/A	none	. N.A. (
					Materials: Wood siding, wood frame construction, concrete / block foundation
\ \/		l	l		
Х		l	l	l	Observations:
					's No major avatam astativar function aspectus noted at time of increation

- No major system safety or function concerns noted at time of inspection.
- No major system safety or function concerns noted at time of inspection.

4. Eaves & Facia

Good	Fair	Poor	N/A	None
Х				



5. Exterior Paint

Good	Fair	Poor	N/A	None	
					Observations:
	X				 Suggest caulking around doors and windows as necessary.

6. Stucco

Good	Fair	Poor	N/A	None
	X			
	^			





Foundation

1. Slab Foundation

Good	Fair	Poor	N/A	None
				Х

2. Foundation Perimeter

X	Good	Fair	Poor	IN/A	None
	Х				

Observations:

• No deficiencies were observed at the visible portions of the structural components of the home.

3. Foundation Walls

Good	Fair	Poor	N/A	None
_				
^				

Observations:

normal settlement



4. Cripple Walls

Good Fair	,,,	None
		Х

5. Ventilation

Good	Fair	Poor	N/A	None	
X			l	l	
/\		l	l	l	1

Observations:

• Screened openings noted.

6. Vent Screens

Good	Fair	Poor	IN/A	None
Х	·			

Observations:

Vent screens noted as functional.

7. Access Panel

Good	Fair	Poor	N/A	None
Х				

Observations:

• The foundation access panel installed and functional during the inspection.

8. Post and Girders

Good	Fair	Poor	N/A	None
Х				

Observations:

- Support Material: Wood/Bearing WallSupport Material: concrete block piers
- Beam Material: Wood
- Concrete piers
- Concrete block/wood piers support floor above.
- No deficiencies were observed at the visible portions of the structural components of the home.

9. Sub Flooring

Good	Fair	Poor	N/A	None
			l	
			l	
			I	I

Observations:

2x6 T and G flooring noted (T and G tongue and groove)

10. Anchor Bolts

Good	Fair	Poor	IN/A	None
X				

Observations:

• The anchor bolte were inspected and appear to be serviceable.

11. Foundation Electrical

G00a_	Fair	Poor	IN/A	None
	Х			

Observations:

• All wiring should be properly secured to the framing.

12. Foundation Plumbing

Good	Fair	Poor	N/A	None
			l	l

Observations:

- 3/4 inch Galvanized
- 1+ inch galvanized
- Cast iron waste and vent pipe noted.
- Galvanized waste and vent pipes noted.
- **OBSERVATIONS**
- Appears Functional at time of inspection.

13. Sump Pump

Good	Fair	Poor	N/A	None
				ΙXΙ

14. Ducting

Good	Fair	Poor	N/A	None
				Х

Grounds

1. Driveway and Walkway Condition

Good	Fair	Poor	N/A	None	Materials, Compute drivery pated a Compute sidewall material
					Materials: Concrete driveway noted. • Concrete sidewalk noted.
					Observations:

 Heavy cracking noted at driveway and some spalling at front of garage and on the inside of the garage



Common cracking

2. Grading

Good	Fair	Poor	N/A	None	Observations
					Observations:
X					• No major system safety or function concerns noted at time of inspection.

3. Vegetation Observations Good Fair Poor N/A None Ol

			Observations:
ΙX			 No major system safety or function concerns noted at time of inspection
			1 INO major system safety of function concerns noted at time of inspection

• Prune or remove any plants that are in contact or proximity to home to eliminate pathways of wood destroying insects.

• Trim trees that are in contact or proximity to home, as branches can abrade roofing or siding.



4808 Pepperwood Way



Back yard

4. Gate Condition

Good	Fair	Poor	N/A	None	
Х					Materials: Wood

5. Patio and Porch Deck

Good	Fair	Poor	N/A	None
				Х

6. Stairs & Handrail

Good	Fair	Poor	N/A	None
				Х

7. Grounds Electrical

Good	Fair	Poor	N/A	None
				\ \ \
			l	X

8. GFCI

Good	Fair	Poor	N/A	None
				Х

9. Main Gas Valve Condition

Good	Fair	Poor	N/A	None	NA - C. Calla
					Materials: west side
X					Observations:

• Meter located at exterior. All gas appliances have cut-off valves in line at each unit. No gas odors detected.

Χ



10. Plumbing Good Fair Poor N/A None Materials Columnia de pining noted
Materials: Galvanized piping noted.
11. Water Pressure
X Pair Poor N/A None Observations: • 65
12. Pressure Regulator
Observations: none
13. Exterior Faucet Condition
X Poor N/A None Location: Front of structure Observations: • Appears Functional.
14. Balcony
Good Fair Poor N/A None X
15. Patio Enclosure
Good Fair Poor N/A None X
16. Patio and Porch Condition
Good Fair Poor N/A None X
17. Fence Condition
Good Fair Poor N/A None Materials: Wood



18. Sprinklers

Good	Fair	Poor	N/A	None
Х				

Observations:

• Home is equipped with an underground sprinkler system. The inspector recommends client consult with home owner for operation instructions and proper winterizing information. Sprinkler systems are beyond the scope of a Home Inspection, due to most of its parts/piping not visible for inspection.



Basement/Crawlspace

1. Walls

Good	Fair	Poor	N/A	None
Χ				

Materials: Crawlspace noted. • A raised perimeter with pier and beam supports -- Crawlspace Observations:

 No deficiencies were observed at the visible portions of the structural components of the home.

2. Insulation

Good	Fair	Poor	N/A	None
				X
				, ,

3. Windows

Good	Fair	Poor	N/A	None
				Х

4. Plumbing Materials

Good	Fair	Poor	N/A	None
Х				

Materials: Appears Functional • Appears Functional Observations:

- Cast Iron
- CopperGalvanized





Galvanized pipes



5. Basement Electric

	Good	Fair	Poor	N/A	None
Г					
П					ΙXΙ
L					


6. GFCI

Good	Fair	Poor	N/A	None
				_
				_ X

7. Access

Good	Fair	Poor	N/A	None	Market Caller 🖶 Garden Lagrage Lagran
					Materials: Exterior hatch door.
X					Observations:

• Exterior entrance is in serviceable condition.



Attic and underfloor access located in master bedroom closet

\sim	\sim	
v	C+ C	rc
() .	Sta	11115

Good	Fair	Poor	N/A	None
				Х

9. Railings

Good	Fair	Poor	N/A	None
				_
				_ X

10. Slab Floor

Good	Fair	Poor	N/A	None
				Х

11. Finished Floor

Good	Fair	Poor	N/A	None
				^

12. Drainage

Good	Fair	Poor	N/A	None
Х				

13. Sump Pump

Good	Fair	Poor	N/A	None
				X

14. Framing

Good	Fair	Poor	N/A	None
				Х





15. Subfloor

Good	Fair	Poor	N/A	None
Х				



16. Columns

Good	Fair	Poor	N/A	None
Х				

Observations:

• No deficiencies were observed at the visible portions of the structural components of the home.



17. Piers

Good	Fair	Poor	N/A	None
\ \ \				
X				

Observations:

• No deficiencies were observed at the visible portions of the structural components of the home.

18. Basement/Crawlspace Ductwork

None	N/A	Poor	Fair	Good
I				
X				

Resid	dentia	l Eart	thqua	ke Hazards Report
Yes	No	N/A	Don't	
Χ			Know	1. Is the water heater braced, strapped, or anchored to resist falling during an earthquake?
Yes	No	N/A	Don't Know	·
Χ				2. Is the house anchored or bolted to the foundation?
Yes	No	N/A	Don't Know	3. If the house has cripple walls:
		X		a. Are the exterior cripple walls braced?
Yes	No	N/A	Don't Know	
		X		b. If the exterior foundation consists of unconnected concrete piers and posts, have they been strengthened?
Yes	No	N/A	Don't Know	
		Х		4. If the exterior foundation, or part of it, is made of unreinforced masonry, has it been strengthened?
Yes	No	N/A	Don't Know	5. If the house is built on a hillside: a. Are the exterior tall foundation walls braced?
		X		a. Are the exterior tail realisation walls braced:
Yes	No	N/A	Don't Know	b. Were the tall posts or columns either built to resist earthquakes or have
		X		they been strengthened?
Yes	No	N/A	Don't Know	
		Χ		6. If the exterior walls of the house, or part of them, are made of unreinforced masonry, have they been strengthened?
Yes	No	N/A	Don't Know	7.7. Kalada a a la cara Prima a cara a c
		Χ		7. If the house has a living area over the garage, was the wall around the garage dooropening either built to resist earthquakes or has it been strengthened?
Yes	No		Don't Know	
			X	3. Is the house outside an Alquist-Priolo Earthquake Fault Zone (zones immediately surrounding known earthquake faults)?
Yes	No	_	Don't Know	
			X	9. Is the house outside a Seismic Hazard Zone (zone identified as susceptible to liquefication or landsliding)?
EXE	CUTE	D BY	' :	
(Selle	er)			(Seller) Date
to one	or mo	re que	eipt of t estions, house	this form, completed and signed by the seller. I understand that if the seller has answered "No", or if seller has indicated a lack of knowledge, there may be one or more earthquake e.
(Buye	er)			(Buyer) Date